


WE GALAXY 1911-SERIES CNC HOP UP CHAMBER

安裝說明 INSTALLATION MANUAL



13
用於TDC模式
Use to TDC mode

NO.	品名 Parts name	NO.	品名 Parts name
1	內腔座/Hop-up chamber	8	套管/Barrel spacer
2	插梢/Pin	9	前管/Front barrel
3	彈簧A/Spring A	10	定位柱/Knob detent
4	橡膠圓柱/Hop-up nub	11	彈簧B/Spring B
5	壓桿/Hop-up lever	12	半圓頭內六角M3X4 X2 Hex socket head cap M3X4 X2
6	O環/O-ring	13	止付M3X5 X3 Set screws M3X5 X3
7	調整輪/Adjustment whell		

